

USCG Auxiliary CHART UPDATING WORKSHEET [Revision 1/1/2008]		General location: Ponaug Marina, Arnold Neck				Vert. Datum		
		Date observed: 12-Apr-08		Sheet No. 1-2		Feet		
		Prepared by: TEAM ONE		Chart Number 13224		Chart Date 1-Nov		Edition 38
		Method used to take FIX: GPS w. WAAS		Model and manufacturer: GARMIN GPS 76 C		Corr. for Transducer (ft) 0.0		
Method used to determine Depth: N/R		Model and manufacturer: N/R						
No. 7	Position Location Number - PLN 6	TEAM ONE		Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task: Define the SHORELINE at the right of the ramp.				N/R		0.0		
Take a fix at the in-shore end of the landmass beside the ramp. Take a photo here.				Latitude	41-41.7758 N		EPE / DOP	
Report Findings and Proof: Shoreline is concrete rubble / rip rap.				41-41-45.90 N (41.7650)		11.5		
Photo 219 shows the boat ramp.				Longitude	071-27.1777 W		Time FIX Taken	
Width of boat ramp is 16 feet. Ramp has an asphalt surface.				071-27-10.60 W (27.1767)		1023		
Recommendation Add the word "RAMP" to chart with an arrow indicating the location of this launching ramp. This LAT/LON defines the edge of the launching ramp. Docking piers along both side of this ramp are two small to chart. A Small Craft Facility report has already been submitted on this ramp and marina.								
No. 8	Position Location Number - PLN 7	TEAM ONE		Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task: Define the off-shore end of small dock at the right of the launching ramp.				N/R		0.0		
Report Findings and Proof: Photo #218 shows the observation.				Latitude	41-41.7686 N		EPE / DOP	
Shoreline is an asphalt ramp. Shoreline has a large boulder in this area.				41-41-46.10 N (41.7683)		11.9		
The edge of the shoreline is characterized as concrete rubble and grass.				Longitude	071-27.1692 W		Time FIX Taken	
				071-27-10.10 W (27.1683)		1024		
Recommendation CAC - Reconfirmed location with a fix on 8/30/08. This LAT/LON defines the edge of the launching ramp. Docking piers along both side of this ramp are two small to chart.								
No. 9	Position Location Number - PLN 8	TEAM ONE		Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task: Take a fix along the shore line.				N/R		0.0		
What comprises the shoreline at this point?				Latitude	41-41.7637 N		EPE / DOP	
Report Findings and Proof: Asphalt ramp. Rip Rap, boulder, soil, and grass.				41-41-45.80 N (41.7633)		11.7		
Reconfirmed location with a new fix on 8/30/08.				Longitude	071-27.1695 W		Time FIX Taken	
				071-27-10.10 W (27.1683)		1024		
Recommendation Plot shoreline as reported. Shoreline is characterized as concrete rubble. This LAT/LON location defines the edge of the shoreline.								
No. 10	Position Location Number - PLN			Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task:						0.0		
Report Findings and Proof:				Latitude			EPE / DOP	
				Longitude			Time FIX Taken	
Recommendation								
No. 11	Position Location Number - PLN			Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task:						0.0		
Report Findings and Proof:				Latitude			EPE / DOP	
				Longitude			Time FIX Taken	
Recommendation								
No. 12	Position Location Number - PLN			Time Depth Taken	Observed Depth	Height of Tide	Depth at Datum	
Describe the task:						0.0		
Report Findings and Proof:				Latitude			EPE / DOP	
				Longitude			Time FIX Taken	
Recommendation								